

# RESTRAINT PLUS+®

## Replacement High Pressure Flow Line Restraints

### Applications

- Frac Iron Securement
- Injection Wells
- Surface Flow Lines
- Surface Valves
- Surface Manifolds

### Warnings

- Not for Lifting
- Shall not be used in temperatures in excess of 194°F, or below -40°F

### Hitch Methods

- Half Hitch
- Spine & Rib

Made in USA



### Size & Pressure Chart

Model	Iron Size	Max Pressure
Restraint Plus+® Red	2"	15,000 psi
	3"	8,000 psi
	4"	5,000 psi
Restraint Plus+® Blue	2"	20,000 psi
	3"	15,000 psi
	4"	10,000 psi
Restraint Plus+® Orange	2"	20,000 psi
	3"	15,000 psi
	4"	15,000 psi

Stocking Distributor:

 **BISHOP  
LIFTING**